

	A	B	C	D	E
1	TECH TIP INDEX 1972 - 2023				
2		SUBJECT	YEAR	MONTH	PAGE
3		<u>MISCELLANEOUS / GENERAL</u>			
4		12 Steps to Restoration	2020	November	17
5		Auto Shop Safety	2015	December	10
6		Buying a Thunderbird	1980	March	11
7		Buying a Thunderbird (same as above)	1986	May	12
8		Buying a Thunderbird (same as above)	2016	April	15
9		Cleaners (Chemicals to Make it Easier)	1978	March	8
10		Corrosion Control	2023	August	23
11		Detailing Tricks - Part I	2014	April	8
12		Detailing Tricks - Part II	2014	May	8
13		Electrical System	2023	September	18
14		Engine Oils - Part I	2008	March	9
15		Engine Oils - Part II	2008	April	8
16		Fluid Leaks	2023	December	21
17		Ford's Part Numbering System	1987	April	6
18		Parts Numbering (Sifting through the Parts Books)	1978	February	8
19		Fire Extinguishers	2012	June	6
20		Fire Safety	2016	January	9
21		Maintenance - Bolt Tightening	1993	July	4
22		Mistakes to Washing Your Car	1996	October	10
23		Motor Oils	1996	July	3
24		Seal Removed Hoses and Lines for Reuse Later	2011	September	7
25		Shop Tools	2017	November	10
26		Spring Checklist	2022	March	19
27		Steel Lines and Rubber Hoses	2022	November	16
28		Tips for T-Bird Trips	2018	March	14
29		Year of Origin License Plates	1986	April	9
30		Year of Origin License Plates	2010	November	4
31		<u>EXTERIOR and TOPS</u>			
32		BUMPERS			
33		Chrome	1977	March	1
34		Chrome	1988	February	10
35		PAINT and TRIM			
36		Painting - Part I	1977	April	4
37		Painting - Part II	1977	August	2
38		Painting Your Bird - Part I	1980	January	7
39		Painting Your Bird - Part IIA	1980	February	6
40		10 Basic Steps for Stainless Restoration	2001	February	3
41		T-Bird Windshield Trim Water Leakage	2011	November	3
42		T-Bird Windshield Trim Water Leakage (same as above)	2016	June	8
43		How to Fix Paint Chips	2023	October	16

	A	B	C	D	E
44		PANEL FIT			
45		Hood Closing	1988	May	5
46		Hinge Lubrication	1993	March	6
47		How to Close Trunk Easier	2014	September	12
48		SUBJECT	YEAR	MONTH	PAGE
49		Hood Opening Troubles	2020	June	12
50		Trunk Hinge Repair	2020	July	11
51		SKIRTS			
52					
53		TOPS			
54		Convertible Top Care	1979	August	4
55		Hardtop	1972	November`	1
56		Soft Top Latches	2002	December	6
57		Rag Top Care	2004	August	5
58		Rag Top Care	2016	March	17
59		Changing Emblems on Hardtops	2014	September	12
60		Soft Top Insulation for Summer Heat	2023	June	20
61		<u>ENGINE and DRIVETRAIN</u>			
62		ENGINE			
63		1955-'57 T-Bird Valve Lash Adjustment	1987	May	5
64		312 Diaper	2018	June	14
65		'57 Cylinder Head Removal	2012	December	4
66		Alternator	1993	April	10
67		Alternator	1996	February	7
68		Engine Balancing an Art	2021	August	15
69		Engine Overheating - Part I	1975	April	2
70		Engine Overheating - Part II	1975	September	3
71		Engine Timing	1976	December	2
72		Engine (and Transmission) Rebuild	1977	June	4
73		Engine Install	1978	May	2
74		Engine Valley Pan Install	1978	September	1
75		Engine Tune Up	1981	September	5
76		Engine Identification - Blocks and Cranks	1990	April	8
77		Engine Fire	1993	April	10
78		Engine Stall	2008	May	8
79		Pre-Lube System Extends Engine Life	1990	February	4
80		Engine Gas/Air Mix	1993	August	8
81		Carburetors	1978	October	8
82		Carburetors (Upgrade)	2015	August	14
83		Holly 4000 Carb	2001	March	5
84		Install a New Acclerator Pump in a '56 (Carb)	2014	July	8
85		Correct Cylinder Head	1978	November	6
86		Dip Stick Accuracy	2018	July	12

	A	B	C	D	E
87		Displacement Disappointment	2019	March	15
88		Generator for 1955 Thunderbird	1997	May	6
89		Generator Testing (and Correct Transmission Fluid)	2002	September	3
90		Heating and Pump Baffle	1994	February	6
91		Ignition Knock	2001	September	6
92		SUBJECT	YEAR	MONTH	PAGE
93		Ignition Knock	2016	May	12
94		Intake Manifold Heat Tube Repair	2017	June	12
95		Milling Heads and Valve Guides	2002	December	6
96		Missing in Action (Engine Miss)	2020	February	15
97		More than You Really Need to Know About Coils	2018	January	10
98		Oil Flow	2020	September	14
99		Oil Pumps	2021	December	14
100		PVC Smog Device (After Market)	2015	July	12
101		Replacing the Rear Main Seal	1995	June	7
102		Rear Main Seal	2002	May	4
103		Rough Engine Idle	1979	March	5
104		Shaky Motor	2019	April	1
105		Spark Plug Servicing	1979	March	6
106		Spark (Vacuum) Advance	2015	April	8
107		T-Bird Running Too Hot	2020	August	10
108		Transmission Support When Removing Engine	2018	May	13
109		Vacuum Leaks	1994	February	5
110		Setting Valves	2010	July	6
111		Valve Lash Adjustment	1984	February	3
112		Valve Lash Adjustment (same as above)	1995	August	4
113		Valve Lash Alternate Method	2001	January	3
114		More on Valve Adjustment	2002	August	6
115		More on Valve Adjustment Methods	2020	May	14
116		Workings of an Engine	2022	July	14
117		BATTERY and ELECTRICAL			
118		12 Volt vs 6 Volt	1996	August	7
119		6 v to 12v Conversion	2002	July	6
120		(Tires and) Battery	1977	May	3
121		Battery Explosion	1979	February	1
122		Battery Chargers	1993	February	7
123		Battery Chargers	1993	April	8
124		Battery Post Corrosion	2003	April	7
125		Battery Post Corrosion - UPDATE	2003	May	2
126		Battery Terminal Cable Connection	2020	December	14
127		T-Bird Battery Replacement	2022	January	19
128		T-Bird Wiring Harness Repair	1997	April	6
129		DISTRIBUTOR			

	A	B	C	D	E
130		Distributor Seal	1978	March	4
131		Distributor Installation	1980	April	7
132		Ignition Timing	2022	February	21
133		FUEL PUMP and FILTER			
134		Air in Fuel Filter Glass Bowl	2011	July	7
135		SUBJECT	YEAR	MONTH	PAGE
136		Electric Fuel Pump Install	2010	August	5
137		Fuel Pumps for Thunderbirds	2011	August	9
138		Fuel Pump Replacement	2014	March	8
139		Gummy Gas	1987	September	15
140		Gasohol (and carbs)	2022	September	16
141		Installing an Electric Fuel Pump	2014	June	8
142		Is Ethanol in Your Gas a Problem	2016	November	11
143		Electric Fuel Pump	2022	May	25
144		RADIATOR and COOLING			
145		Cooling System Information	2021	April	17
146		Overheating Explained	2001	July	4
147		Overheating	1978	January	4
148		Engine Cooling	1987	November	4
149		Engine Cooling	1993	May	6
150		T-Bird Cooling	1996	June	8
151		Over Heating	2011	April	7
152		Position of Fan	2011	February	5
153		Position of Fan (same as above)	2016	September	11
154		Radiator Hoses	2011	June	7
155		Radiator Hoses (same as above)	2017	September	16
156		T-Bird Running Hot in the Summer	2015	September	11
157		Thermostat Housing Repair	2017	May	19
158		Thermostat Replacement	2020	March	12
159		More About Thermostats	2020	April	7
160		Thunderbird Overheating	2019	September	15
161		STEERING			
162		Ball Joints	2002	January	7
163		Handling Problems	2001	June	2
164		Steering	1978	July	4
165		Power Steering - Storage	1978	July	4
166		Power Steering Cylinder Seal	2015	June	11
167		TRANSMISSION			
168		(Engine and) Transmission Rebuild	1977	June	4
169		(Generator Testing and) Correct Transmission Fluid	2002	September	3
170		Transmission Support When Removing Engine	2018	May	13
171		Standard Transmission (Install Detail)	2022	June	19
172		Cruis-O-Matic Transmission Swap	2023	March	21

	A	B	C	D	E
173		VALVE COVERS and AIR CLEANER			
174		Valve Cover Detail	2017	July	11
175		<u>UNDERCARRAGE</u>			
176		BRAKES			
177		Safe Brake Fluid	1978	February	6
178		Brake System Vapor Lock	1978	September	6
179		SUBJECT	YEAR	MONTH	PAGE
180		Brake System Vapor Lock (same as above)	1986	August	7
181		Stop Light Switch Leaking	1978	December	5
182		Brake Safety	1979	March	6
183		Brake Fluid	1988	January	8
184		Silicone Brake Fluid	1988	March	12
185		Brake Fluid Comparison	1989	December	12
186		Brakes	2002	November	3
187		Brakes (same as above)	2016	July	13
188		Brakes Pulling to the Right (Brake Lining)	2011	January	5
189		Mechanical Brake Switch	2014	December	9
190		Stop Light Switch Options	2016	December	12
191		Brake Light Switch	2018	April	17
192		EXHAUST			
193		Exhaust System	1977	July	2
194		Exhaust Leaks	1992	December	3
195		Exhaust Manifold Leak	2008	January	7
196		Exhaust Control Valve (Heat Riser)	2021	July	18
197		SUSPENSION			
198		Shock Absorbers	1989	February	11
199		Is Your Bird Level - Part I	1990	November	3
200		Is Your Bird Level - Part II	1990	December	3
201		Leveling Up Your Bird	2008	December	7
202		Suspension	2002	March	8
203		Tech Surprise (Coil Springs)	2020	November	16
204		Sway Bars for Little Birds	2023	February	12
205		Sway Bar Installation Update	2023	April	17
206		TIRES and WHEELS			
207		1957 Thunderbird Wheels vs Station Wagon & Pass..	2018	November	9
208		Radial Wide White Wall Tires	2018	December	15
209		Rear Wheel Bearing	1994	June	7
210		Tires and Wheels	2008	August	5
211		Tires Bias-Ply vs Radial	2015	March	13
212		Tires Bias-Ply vs Radial (same as above)	2020	January	15
213		UNDERCARRAGE			
214		Undercoating and Sound Deadner	1989	April	8
215		<u>INTERIOR</u>			

	A	B	C	D	E
216		UPHOLSTERY			
217		Upholstery	1977	February	2
218		CARPET / TRIM PANELS			
219		Windlace	2015	October	12
220		DASH and INSTRUMENTS			
221		Bulbs and Fuses	1986	September	3
222		(Radio and) Clock	1977	September	4
223		Cigarette Lighter	1978	January	1
224		SUBJECT	YEAR	MONTH	PAGE
225		Glove Box Door Trim	2021	March	14
226		Headlight Switch Knob Removal	1978	August	8
227		Ignition Switch Wiring	2022	April	18
228		Instrument Rejuvenation	1990	May	6
229		Oil Light On	2011	March	8
230		Oil Light On (same as above)	2016	October	10
231		Speedometer Accuracy	1993	October	8
232		Tachometer Repair	2022	August	14
233		Temp Guage	1987	February	6
234		T-Bird Dash Clock	1993	January	5
235		To Quartz or Not to Quartz (CLOCK)	2004	April	5
236		Working Under the Dash	2022	October	15
237		Eliminating Dim Dash Lights	2023	January	15
238		DOOR LATCHES			
239		'55/'56 Door Striker Plates	2001	May	4
240		Hinge Lubrication	1993	March	6
241		Lock Lubricant	1993	May	6
242		Lock Links (Door Locks)	2015	February	11
243		Door Latch Modification	2015	May	11
244		Door Striker Plate Adjustment	2023	May	18
245		HEATER and AIR CONDITIONING			
246		Heater Controls	1978	October	6
247		Heater Output	1993	April	10
248		Heater Core Fix and Repair	2020	October	12
249		How to Improve Defroster without Air Conditioning	2014	October	10
250		Saving Face (Heater Control Face Plate)	2019	August	13
251		Sealing Up that T-Bird	1995	September	5
252		Sealing the Heater for Summer Driving	2016	February	11
253		A/C Compressor Relocation for Improved V-Belt Perfo	2021	September	22
254					
255		Water Control Valve - Alternate	2002	October	4
256		RADIO			
257		Antenna Install	2022	December	14
258		Radio (and Clock)	1978	September	4

	A	B	C	D	E
259		Radio Antenna Trimmed	1978	July	4
260		Speed Compensated Volume Control Radio	1978	December	5
261		Radio On/Off Switch Repair on Early Tube Radio	2014	October	10
262		SEAT			
263		Electric (Window or) Seat Switch	1978	December	5
264		Power Seat Modifications	2021	June	16
265		Three Point Shoulder Seatbelt System	2014	February	8
266		SHIFTER			
267		Neutral Safety Switch	2003	March	5
268		TURN SIGNALS			
269		Turn Signal Trouble	2021	February	11
270		SUBJECT	YEAR	MONTH	PAGE
271		WEATHERSTRIPING			
272					
273		WINDOWS			
274		Glass	1977	October	4
275		Electric Window (or Seat) Switch	1978	December	5
276		Power Window Conversion	2006	April	5
277		Window Mechanism (2 articles)	2002	February	4
278		Window Adjustment	2012	January	3
279		Window Adjustment (same as above)	2016	August	13
280		All the Way Up (Window Adjustment)	2012	February	5
281		Sun Visor Fix	2017	August	15
282		OTHER			
283		TRUNK MAT and JACK			
284					
285		WIPERS			
286		Wiper Repair	1978	January	2
287		Wiper Motor	2011	May	7
288		Windshield Wipers	1997	October	4
289		Using Brake Fluid to Improve Wiper Performance	2014	August	10
290		ACCESSORIES			
291		Cruise Control	1991	August	3
292		AIR DUCTS			
293		Air Duct Restoration	1994	May	6
294		Ventilation	2023	July	17
295		HORNS			
296		Rejuvenating Old Horns	2001	July	4
297		Horn Ring Restoration	2015	January	8
298		T-Bird Horns	2021	November	20
299		Lights			
300		Headlight Adjustment	2020	January	16
301		Lights (Headlights and Turn Signals)	2008	July	5

	A	B	C	D	E
302					